

Thornton Safety and Inspection, LLC

Website: <http://www.thorntoninspection.com>

Email: Sean@thorntoninspection.com

Phone: (601) 259-6859 • (601) 214-6569

Inspector: Sean Thornton



Move-In Certified Property Inspection Report

Client(s): Sample

Property address: Meridian, MS

Inspection date: 3/27/2012

This report published on Thursday, March 29, 2012 9:44:43 AM CDT





[View summary page](#)

This report is the exclusive property of this inspection company and the client(s) listed in the report title.

How to Read this Report

This report is organized by the property's functional areas. Within each functional

area, descriptive information is listed first and is shown in bold type. Items of concern follow descriptive information. Concerns are shown and sorted according to these types:

	Safety	Poses a risk of injury or death
	Repair/Replace	Recommend repairing or replacing
	Evaluate	Recommend evaluation by a specialist
	Comment	For your information

[Click here](#) for a glossary of building construction terms.

***Corrected defects are indicated in BLUE beside the picture of the defect and are summarized on the [Summary Page](#).**

Table of Contents

[General information](#)

[Exterior](#)

[Roof](#)

[Attic](#)

[Electric service](#)

[Water heater](#)

[Heating and cooling](#)

[Plumbing and laundry](#)

[Kitchen](#)

General information

Inspector's name: Sean Thornton

Type of building: Single family

Age of building: 3 years

Present during inspection: Property owners

Occupied: Yes

Weather conditions: Clear

Temperature: Warm

Ground condition: Dry

Front of structure faces: East

Main entrance faces: East

Foundation type: Slab on grade

The following items are excluded from this inspection: Security system

Exterior

Foundation material: Poured in place concrete

Apparent wall structure: Wood frame

Wall covering: Brick veneer

Driveway material: Poured in place concrete

Sidewalk material: Poured in place concrete

Exterior door material: Solid core wood, Glass panel



1) 13)  Recessed "can" lights that are not rated for contact with insulation are installed in the ceiling below the attic. One or more of these lights are in contact with insulation. This is a fire hazard. Insulation should be moved, and wells or barriers should be installed or repaired as necessary to keep the insulation away from these lights as per the manufacturer's installation instructions.

Photo 70

CORRECTIONS VERIFIED
4/10/12



Warning label indicating that light is to be kept clear of insulation by 3"

All recessed can lights were replaced with IC lights rated for contact with insulation.
Arrow indicated IC rating



Photo 20
Recessed lights in front porch ceiling



Photo 21
Recessed lights in front eave area



Photo 24
Recessed lights in rear porch ceiling



Photo 50
View from the attic of recessed can lights around the exterior

2) West side of house and deck area



Photo 19



Photo 23
Deck stairs and railing



Photo 25
View of the grading underneath the deck

Electric service

Primary service type: Underground

Primary service overload protection type: Circuit breakers

Service amperage (amps): 200

Service voltage (volts): 120/240

Location of main service switch: On exterior north wall of house

Location of sub panels: One sub panel located in garage utility closet

Location of main disconnect: All breakers in outside service panel and a 200 amp disconnect at top of sub panel

Service entrance conductor material: Aluminum

System ground: Ground rod(s) in soil

Main disconnect rating (amps): 200

Branch circuit wiring type: Copper

Solid strand aluminum branch circuit wiring present: No

Smoke detectors present: Yes




5)    Neutral wires are doubled or bundled together on the neutral bus bar. This is unsafe due to the need to turn off multiple circuit breakers to work on any of the circuits using these wires. A qualified electrician should evaluate and repair as necessary.



Photo 33

View of sub panel with cover removed for inspection. Circle indicates area where neutral wires were doubled

**CORRECTIONS
VERIFIED 4/10/12**




Photo 34

Neutral wires have been separated into individual connections.




Photo 2
Infrared image of sub panel showing that breaker and conductor temperatures were normal




Photo 3
Infrared image of sub panel showing that breaker and conductor temperatures were normal



Photo 15
Electrical service and meter located on north wall




Photo 16
Main electrical service disconnect breakers located below meter

Kitchen


10)  One electric receptacle that serves countertop surfaces within six feet of a sink appear to have no ground fault circuit interrupter (GFCI) protection. This is a safety hazard due to the risk of shock. A qualified electrician should evaluate to determine if GFCI protection exists, and if not, repairs should be made so that all receptacles that serve countertop surfaces within six feet of sinks have GFCI protection. For example, install GFCI receptacles or circuit breaker(s) as needed.



Photo 36

Receptacle on left side of kitchen sink did not trip during GFCI test

CORRECTIONS VERIFIED
4/10/12



Photo 37

Receptacles replaced with working GFCI's.

11)



Photo 39

Kitchen range in operation



Photo 40

Above range microwave with fan

Photo 41

Filters for the above range fan

Roof

Roof inspection method: Viewed from eaves on ladder

Roof type: Hipped

Roof covering: Asphalt or fiberglass composition shingles

Estimated age of roof: 3 years

Gutter & downspout material: Aluminum

Roof ventilation: Adequate

3) Pictures of the roof area and gutters



Photo 9
View of the east side showing architectural shingles with no defects noted and gutters that were clear with no debris or standing water



Photo 10
Architectural shingles on the east side with no defects noted



Photo 11
East side showing valley roofing method referred to as a cut valley



Photo 12
View of ridge vent caps from the east side



Photo 13
Close-up view of valley and ridge vents
on the east side



Photo 14
Overhead view of gutters and valley on
the east side



Photo 26
Sewer vent on the west side



Photo 27
View of valley and guttering on west side



Photo 28
Close-up view of ridge vents from the west side



Photo 29
View of vinyl soffit covers with slots for ventilation

Attic

Inspection method: Partially traversed

Roof structure type: Rafters

Ceiling structure: Ceiling beams

Insulation material: Fiberglass loose fill

Insulation depth: 10" in most areas except around the eaves and over unconditioned spaces

Insulation estimated R value: 22

-
- 4) **i** Some attic areas were inaccessible due to lack of permanently installed walkways, the possibility of damage to insulation, low height and/or stored items. These areas are excluded from this inspection.



Photo 46
Attic area



Photo 48
Showing depth of insulation measured at around 10" in accessible areas



Photo 45
View of framing in attic



Photo 47
View of framing in attic



Photo 49
Attic area

Water heater

Estimated age: 3 years

Type: Tank

Energy source: Electricity

Capacity (in gallons): 50

Manufacturer: Rheem

Model: 82v52-2

Water temperature (degrees Fahrenheit): 115

7)




Photo 5

Hot water temperature in bathrooms was around 113 degrees F.



Photo 6

Hot water temperature in the kitchen was around 113 degrees F.



Photo 42

Water heater label

Photo 43

View of water heater supply lines and piping for the TPR valve

Heating and cooling

Estimated age: 3 Years

Primary heating system energy source: Electric

Primary heat system type: Horizontal draft

Primary A/C energy source: Electric

Primary Air conditioning type: Split system

Distribution system: Sheet metal ducts

Manufacturer: Goodman

Filter location: In return air duct below furnace, Behind return air grill

8)




Photo 4
The cooling system supplied a consistent 59 to 60 degrees F.




Photo 7
Temperature of cold air return




Photo 51
The heating system supplied a temperature at the supply register around 115 degrees F.




Photo 8
Temperature of the hot air return



Photo 17
Outside AC compressor



Photo 18
Data plate on outside AC compressor



Photo 44
Horizontal furnace located in attic

Plumbing and laundry

Water pressure (psi): 62

Location of main water shut-off valve: At the street

Location of main water meter: At the street

Water service: Public

Service pipe material: Not visible

Supply pipe material: Polyethelene

Vent pipe material: Plastic

Drain pipe material: Plastic
Waste pipe material: Plastic

9)



Photo 22
Water pressure measured at outside faucet




Photo 32
Water control manifold located in the garage utility room



Photo 35
View of under sink areas in bathrooms with no sign of water leakage



Photo 38
View of under sink area in kitchen with no sign of water leakage



Infrared showing no blockages during hot water drainage in pipes under sinks